

SUPSI

Investigations on the Main Causes for Reduced Performances during the Early Stage of Life of Rooftop PV Systems

Mauro Caccivio


University of Applied Sciences and Arts of Southern Switzerland (SUPSI),
Institute for Applied Sustainability to the Built Environment (ISAAC)
Head of SUPSI PVLab
Email: mauro.caccivio@supsi.ch

Domenico Chianese

University of Applied Sciences and Arts of Southern Switzerland (SUPSI),
Institute for Applied Sustainability to the Built Environment (ISAAC)
Senior researcher SUPSI PVLab
Email: domenico.chianese@supsi.ch

Summary

- Introduction
- Purpose of the project
- Overview
- Results
- Conclusions



Source: SUPSI




Introduction



Introduction



Source: freesuns.ch




Source: 3s-solarplus.ch

Many Swiss BIPV photovoltaic manufacturers:
the future is bright ! But...



Source: .solararchitecture.ch



Source: .sunstyle.ch

Introduction



...are we able to reach 40 years of production and beyond?!


TISO PV Plant, first grid connected PV in Europe in 1982. Source: .supsi.ch

Purpose

- **Several PV systems with poor energy production**
 - The lifespan of a rooftop PV plant can be estimated **around 25-30 years**, while the oldest plant in Europe, installed at SUPSI, has exceeded 35 years of life.
 - As in any system, defects and problems typically occur in the early years and at the end of life of the system itself.
- **What are the main causes for reduced performance ?**

The objectives of the project were manifold:


- Identify, classify and prevent defects that emerge **after the first years of operation** (≤ 5 years).
- Correlate them with power at the beginning of life.
- Improve knowledge of observed early stage defects in order to **reduce costs and risks** for both systems' owners and installers.



Actions:

- Risk reduction, both for existing and newly installed plants.
- Improve the quality, lifespan and reliability of photovoltaic systems in ticino
- Improve system level performance
- Accelerate the return on investment

Purpose: framework



Classi [kW]	N° impianti a fine 2019		Potenza a fine 2019 [kW]	
0-10	3'535	(71.5%)	24'043	(26.9%)
10-30	1'134	(22.9%)	19'919	(22.3%)
30-100	158	(3.2%)	9'300	(10.4%)
100-1000	114	(2.3%)	30'162	(33.7%)
>1000	4	(0.1%)	6'033	(6.7%)
Totali	4'945	(100%)	89'456⁴	(100%)

Where:

- Ticino, South of Switzerland
- 350'000 inhabitants
- > 5000 PV systems installed
- \approx 90MW power (STC)
- **260W / inhabitant**

Goal: > 330 MW (out of 880MW possible on rooftop)

Subsidies for PV Systems and renewables energy:

- Swiss subsidies +
- Regional subsidies:
 - **FER: Renewable Energy Fund**
- **FER control of the injected energy**

Purpose: durability and reliability, focus points

Durability and reliability of photovoltaic systems depend on many factors:

- Quality of components (modules, but not only, also: inverters, connectors, etc.)
- Quality of dimensioning and design
- Quality of installation execution
- Quality of maintenance
- Climatic conditions
- Neighborhood conditions

Main topics for the rapid adoption of the PV:

- Drastic cost reduction
 - New technologies adopted
 - New installation systems
- Rapid growth of number of PV installations
 - Lack of knowledge of technologies
 - Lack of monitoring and controls

Quality affects different stakeholders in the value chain:

- Module and inverter and other components' manufacturers
- PV system installers
- Investors
- Owner of PV systems

Overview: method

LISTA DI CONTROLLO DELLE CONDIZIONI DEI MODULI E DEGLI INVERTER										PAGINA 8	
RAPPORTO D'ISPEZIONE IMPIANTO										PAGINA 4	
MISURE IMPIANTO - OMBRE										PAGINA 5	
Numero Rapporto : _____ ISAAC 19-S03-07, FER 310034										05.06.2019	
Data dell'ispezione: _____ 29.03.2019 alle 13e30										12.06.2019	
Data del termine rapporto: _____ 04.06.2019										Approvato	
Azimuth: _____ SE Inclinazione _____ 10°										X	
Cablaggio serie (pannelli)		Type _____	Cablaggio serie (box stringhe - inverter)	Type _____	Pos (mm2) _____ 6	Neg (mm2) _____ 6	Soccorso	X	su tutti i lati		
		Pos (mm2) _____ 4		Pos (mm2) _____							
Fusibili della serie		Type _____ 10x38 gPV	Sezionatori DC	Type _____	Rating (A) _____ NA	DC rating (V) _____ NA	Localizzazione	(X)	crepe		
		Rating (A) _____ 25		Rating (A) _____							
Potenza Moduli [W]		DC rating (V) _____ 900	Sezionatori DC	DC rating (V) _____ NA	9.21 A	4505 W	Approvato	X	maggiore (minuta)		
		Capacity (kA) _____ 30		DC rating (V) _____							
Quantità Moduli _____ 68		Voc (stc) serie _____ 653 V	Isc (stc) serie _____ 9.21 A		Pmpp (stc) serie _____ 4505 W		Approvato				
Moduli per stringa _____ 17		KACO Powerdior 20.0TL3-INT		Serial number _____ 20.0TL01449600		Functioning OK _____ OK		X			
MISURE PRATICHE DELLE SERIE										X	
String		String reference	1.1.1 + 1.1.2	1.2.1 + 1.2.2				X			
Test di isolamento e dei parametri		Voc (V)	593	590				X			
		Isc (A)	13.35	13.37				X			
Misure effettuate con:		Test voltage (V)	1000	1000				X			
Benning PV 1-1		Pos/Neg - Earth (MOhm)	98	93				X			
CR6 e cella di riferimento		Irraggiamento (W/m2)	688	688				X			
Controllo polarità (inverter ON)		Pos - Neg (V _{max})	505	498				X			
Misure effettuate con:		Pos - Earth (V _{max})	167	162				X			
Multimetro Fluke 177		Neg - Earth (V _{max})	-338	-337				X			
Curve IV		Misure effettuate con:	Tritec - TRIKA		Doc - Link: riassunto				X		
Indicazione stringhe ombreggiate		1.1.1	1.1.2	1.2.1		1.2.2		X			
1 Camini:		Ovest						X			
2 Alberi:		Ovest	Ovest					X			
3 Case adiacenti:								X			
4 Autombreggiamento shed (h)								X			
5 Ombre da cavi, pali, ecc.								X			
6 Erbe, cespugli								X			
Orizzonte: _____ Descrizione dell'orizzonte, oppure se l'orizzonte sembra problematico										X	
Alberi verso OVEST che influenzano in particolare la stringa 1.1. Meno drasticamente la stringa 1.2.										X	
Il cammino di irradiazione in mezzo alla stringa 1.1.1 non crea ombre sui moduli.										X	
Foto: Link Alberi										X	
Polvere e sporco: _____ Sporcizia sui moduli? Presenti Hot-spot sul bordo basso dei moduli?										X	
Due sassi della ghiaia trovati su un modulo										X	
La sporcizia è presente in particolare verso il lato inferiore del modulo in modo non omogeneo. Crea hot-spot importanti, in particolare localmente ed in alcuni casi su celle complete.										X	
Foto: Link Sassi										X	


Checklist measurements:

- Measurement of the I-V characteristic of the string (I-V tracer); extrapolation to STC.
- Measurement of insulation (Riso), Voc and Isc.
- Polarization measurement (i.e. PID)
- Thermographic analysis (where possible)
- Visual analysis of the PV modules (where possible)
- Partial shadow analysis
- System and BOS analysis (inverters, string boxes, connectors, cables,...)
- Documentation

An energy production analysis is not carried out!

Overview: approach and limits

- 30 rooftop PV systems were tested (out of a total of approx. 4200 plants in Ticino)
- **Only 1.4%** of the installed power in Ticino in 2018
- built in the last 5-7 years.
- Measurements and checklist in accordance to international standard



30 rooftop PV systems examined in Canton Ticino, South of Switzerland

Limits of the project:

- Only PV plants with FER control of the energy fed into the grid
- Not an exhaustive statistic
- Self-consumption does not always allow a correct preliminary analysis
- Limited measurement and analysis time available
- Access to roofs not always possible



Overview: measurements

- A total of 560 strings were checked (I-V curve measurement, insulation measurement, visual inspection, etc.).
 - 360 pictures with **infrared thermography** (IRT) were taken on half of the PV plants (14 out of 30 PV plants).
 - The **visual inspections** were carried out directly or with the help of a drone.
 - The traceability of defects was limited by the difficulty in accessing the roofs, in particular the pitched ones (limits in detailed visual inspection and infrared thermography).
- About 560 I-V curve with HALM and TRIKA IV curve tracers
 - About 560 insulation measurement with Benning PV 1-1



Overview: 30 PV systems - 1.1MW measured

- **29** systems inspected **less than 5 years old**
- **1** system inspected 22 years old
- **Power classes:**
 - < 5kW: 4
 - < 15kW: 7
 - < 30kW: 8
 - > 30kW: 11
 - TOTAL: 1.1 MW
 - (1.4% of the 79MW installed up to the end of 2018)
- **Type of roof:**
 - Pitched roof: 14
 - Flat roof: 15
 - BIPV: 0
 - Field: 1 (the 22 years old system)
- **Cell types:** sc-Si and mc-Si with 2BB or 3BB, one system with half-cut cells.
- **Type of plant:** on-grid, in self-consumption
- **Inverter type:**
 - Central Inverter with one or more MPPTs: 26
 - String Inverter: 3
 - Optimiser: 1
- Number of **strings** per plant:
 - Mean: 9.8
 - 1 to 42 (96)
- Number of inverters per plant:
 - Mean: 1.7
 - 1 to 6 (16)

RESULTS

Types of defects / errors / system failures found

The types of defects, errors or faults encountered during the analyses can be grouped into four different areas:

1. Errors in the **design** of the system
2. Plant or component **construction** errors (wiring, cables and connectors, modules, inverter ...)
3. **Maintenance** problems (soiling, fault traceability, lack of monitoring...)
4. **Aging** defects (faults, hot-spots, burns or oxidations in cells or connectors, ...)


Occurrence of defects / errors / failures:

- **Soiling** is by far the most frequent problem encountered
 - 24 dirty plants
 - 3 clean plants
 - 3 n.a.
- Temporary partial shadows
 - Present in more then **50%** of the plants
- Permanent partial shadows
 - **In 16.7 % of the plants**
- Strings disconnected: **3 out of 203**

	Defects/Errors/Failures in strings	
1	Power Degradation (STC)	96.5 %
2	Soiling on modules	88.9 %
3	Partial shadows	53.3 %
4	Permanent partial shadows	16.7 %
5	Defects / dirt in the inverter	10.0 %
6	Broken glass	3 modules
7	Strings disconnected	1.4 %



Note: Thermography was not possible to systematically analyze the presence of hot spots in all plants.

Power differences, $P_{\max_measured}$ (STC) vs. $P_{\max_nominal}$ (STC)



Design issues

- **Permanent** partial shadows!
 - Mutual shadows
 - Chimneys
- **Temporary** partial shadows:
 - Chimneys
 - Trees
 - Poles
 - Antennas
- and corresponding **electrical wiring**



I-V curve with module permanently shaded (measure and STC)

Design issues, some examples:





Mutual shadows



Tree shadows




Near building shadows




Chimney shadows

Construction and wiring defects and errors

- Incorrect number of modules in the string
- Changes in layout or position of the modules
- Incorrect wiring of dummy (spare) modules



Cell defects



Dummy module in Isc instead Voc



Layout and wiring error



Poor wiring

Only few construction or wiring defects



Maintenance issues: examples



Dirty Inverter filter: derating in power



Soiling on bottom edge in proximity to the ground:




Soiling on the bottom edge of the modules can cause hot spots




Maintenance issues: soiling



- No hot-spot but lower performance (e.g. -30%)
- Soiling is not always uniform but heterogeneous: it can accumulate in some parts of the modules or of the strings
- Farms and agriculture are more sensitive




Maintenance: modules tilt angle on flat and pitched roofs







- Modules tilt angle:
 - Mean: 14.2°
 - Min: 3°
 - Max: 30°
- The decrease in tilt angle, increases soiling problem

Aging defects or glass breakage: examples

- Damage to the cell or glass (browning, broken glass, delamination , etc ...)
- Loss of power (transparency of the glass, current, ...)
- Activation of the by-pass diode
- Hot-spots



Short circuit / lightning or hot spot ?



Hot spots can cause broken glasses

...and browning cells

Conclusions

- The **30 PV plants** (1.4% of the power installed in Canton Ticino, Switzerland), were chosen from those with reduced production or already with indications of defects, built in the last 5-7 years:
2/3 less than 30kW
- 4 different types of defects, errors or faults found: errors in the **design** of the system / Plant or component **construction** errors / **maintenance** problems / **aging** defects
- «**Design**» and «**Maintenance**» are the two main causes of functional defects in plants and lower performance.
- «**Soiling**» is by far the most frequent problem encountered. It is a maintenance issue but also a design issue (tilt angle).

Conclusions/Suggestions



Source: swissolar.ch

The **installer** should care for:

- Limit partial shadows
- Avoid permanent shadows
- Increase knowledge in design

The **owner** should care for:

- Monitoring (monthly values but at least annual value)
- Comparing (with expected simulated performance)
- Annual maintenance (cleaning modules and inverter filters, cutting trees and hedges)

Thanks to:



- Cantone Ticino, Fondo Cantonale FER
- Ufficio dell'energia del cantone Ticino



- Energieschweiz

- Team ENGINEERING ISAAC: Enrico Burà, Boris Margna, Nicolas Ostinelli
- Team PVLAB - ISAAC: Gabi Friesen

Questions

